From glowbugs@sco.theporch.com Tue Apr 22 23:33:23 1997

Return-Path: <glowbugs@sco.theporch.com>

Received: from sco.theporch.com (sco.theporch.com [207.234.31.38])

by uro.theporch.com (8.8.6.Beta0/A-UX3.1.1) with ESMTP id XAA11707

for <shimshon@uro.theporch.com>; Tue, 22 Apr 1997 23:33:20 -0500 (CDT)

From: glowbugs@sco.theporch.com

Received: from sco.theporch.com (localhost [127.0.0.1])

by sco.theporch.com (8.8.6.Beta0/SCO-5.0.2) with SMTP id EAA12523;

Wed, 23 Apr 1997 04:31:18 GMT Date: Wed, 23 Apr 1997 04:31:18 GMT

Message-Id: <199704230431.EAA12523@sco.theporch.com>

Errors-To: ws4s@infoave.net

Reply-To: glowbugs@sco.theporch.com Originator: glowbugs@sco.theporch.com Sender: glowbugs@sco.theporch.com

Precedence: bulk

To: Multiple recipients of list <glowbugs@sco.theporch.com>

Subject: GLOWBUGS digest 511

X-Listprocessor-Version: 6.0 -- ListProcessor by Anastasios Kotsikonas X-Comment: Please send list server requests to listproc@sco.theporch.com

Status: 0

GLOWBUGS Digest 511

Topics covered in this issue include:

1) MOTORBOATING

by leeboo@ct.net (Leon Wiltsey)

Date: Wed, 23 Apr 1997 00:32:00 -0400 (EDT)

From: leeboo@ct.net (Leon Wiltsey)

To: GLOWBUGS@theporch.com Subject: MOTORBOATING

Message-ID: <199704230432.AAA07953@blue.ct.net>

Hi Gang

Got a problem, filter cap got here and installed in regen power supply. Now the audio section motorboats at mid to high volume levels. Have tried everything I know, decoupled 6s17 plate supply from 6aq5 and it did not help much.. b+ now 265 volts with less than .35 ripple. Any ideas?

Thank the good LORD for all that you have!!!

Leon B Wiltsey jr. (Lee) 4600 Lake Haven blvd... Sebring fl 33872.....

68yr old retired semi disabled senior (stroke got my balance and coordination) formerly w4kcj & kp4ryb (till I quite) dumb dumb waiting for my tech+ lic to arrv 73's play keyboard and sing music 1920's to 60' none of the 80'S- 90'S noise